

The Government of The Bahamas



Report on An Environmental Assessment at the Vopak Bahamas Terminal former BORCO Freeport, Grand Bahama

**PRESENTED BY THE ENVIRONMENTAL MONITORING AND RISK
ASSESSMENT DIVISION (EMRAD) AT THE DEPARTMENT OF
ENVIRONMENTAL HEALTH SERVICES (DEHS),
MINISTRY OF ENVIRONMENT**

November 2009

**Submitted by
Anthony Ryan
Senior Laboratory Technologist**

Vopak Facility showing part of the old BORCO Refinery



MEMORANDUM

**MINISTRY OF THE ENVIRONMENT
DEPARTMENT OF ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL MONITORING AND RISK ASSESSMENT
P.O. Box SS-19048
TEL: 322-2845/326-67295/326-7128
FAX: 323-3863**

To: Mr. Ronald Thompson
Permanent Secretary
Ministry of The Environment
Nassau, Bahamas

Your reference:

Our reference: /DEHS/EMRAD/15/1

Date: November 13, 2009

u.f.s. Mr. Winston Sweeting
Acting Director - DEHS

u.f.s. Mr. Dwayne Curtis
Assistant Director - EMRAD

**RE: Report on environmental assessments carried out at Vopak Bahamas
Terminal the former BORCO, Freeport, Grand Bahamas**

Please see attached a report on an environmental assessments carried out at Vopak Bahamas Terminal the former BORCO, Freeport, Grand Bahamas.

Anthony Ryan
Sr. Laboratory Technologist

/ar

TABLE OF CONTENT

1.0	Executive Summary	1
2.0	Introduction	7
2.1	Vopak	7
2.2	Freeport Industrial Park	8
3.0	Environmental Assessment Methodology	9
4.0	Results	11
4.1	Interview Process	11
	Phase 1: Meeting at the office of the Grand Bahamas Port Authority	11
	Phase 2: Visit to Vopak Facility	12
	<i>Cause(s) of a recent Fire</i>	13
	<i>Ambient air odors (Said to be possible trans-boundary emissions)</i>	15
	<i>Smoke stack emissions</i>	16
	<i>Tank Blasting</i>	16
	<i>Other Industrial Facilities</i>	16
	<i>Oil in water (Oil in piped water in Pinder's Point)</i>	17
	<i>Monitoring groundwater well</i>	17
	<i>General Inquiries</i>	17
	Phase 3: Interview of residents	19
	Phase 4: Interview The Grand Bahama Utility Company Limited	20

	Health care providers (Concerning types of illnesses seen etc)	21
	Phase 6: Testing	22
	Phase 7: Tour of Vopak Facility	23
5.0	Discussion	24
6.0	Conclusion	26
9.0	Recommendations	27
	Appendix A: Grand Bahama Utility Company Limited	
	Appendix B: Vopak Information	
	Appendix C: Digital Photographs	
	<ul style="list-style-type: none">• Tour of the Vopak Facility• Handling of wastewater• Location of fire• Groundwater Monitoring wells• Old BORCO Refinery• First aid station, fire trucks and ambulance• Grand Bahama Utility Company Limited• Health Care Facility• Resident's Home visited• Other Industrial Operation	